Date: 27 3)25

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 002

It is certified that an inspection team headed by Pavithra BS Sr. Analyst RDWSD District Laboratory Bangalore (Name of Officers with designation) from RDWSD District Laboratory Bangalore (Name of Department/Office) inspected the Deeksha STEM School (Name & Address of the School)Bangalore - 560060 on 25-03-2025 and found that the Deeksha STEM School No.10/3E, Kengeri-Kommaghatta Road, Bangalore-560060 (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of 24-03-2026

Name Designation

Signature with Seal Testi

To

Deeksha STEM School No. 10/2E, Kengeri-Kommoghatta Boad Bangalore-Choolo

DEEKSHA STÈM SCHOOL DEEKSRY.NO,10/3E, Kommaghatta - Kengeri Road Koma Kengeri (H&P), Bengaluru - 560060

Radlike DP

PRINCIPAL DEEKSHA STEM SCHOOL SRY.NO,10/3E, Kommaghatta - Kengeri Road

Kengeri (H&P), Bengaluru - 560060